Please complete every section daily and give to at ENV Station 001.

Date: 3/22/17Time: 3.00 P.m Initials: TRP

Outfall 009/010	Answers
Substance discharged?	Y / (N)
-If Yes, Color?	
-If Yes, Size / Area?	
Vac truck amount recovered	0
Estimated oil recovered	
Length of sorbent boom replaced	
Canal Appearance (winds, sheen, etc.)	n.E - 15-20mgh

Date: 3/22/17
Time: 9:05 0.m
Initials: 127

Outfall 001	Answers		
Substance discharged?	Y / (N)		
-If Yes, Color?			
-If Yes, Size / Area?			
Vac truck amount recovered			
Estimated oil recovered	0		
Length of sorbent boom replaced	0		
Canal Appearance (winds, sheen, etc.)	D.E - 15-20 md.		


Very light steen within the Smel west.

08-22-16;08:58AM;

Pit covers must remain on at all times

Date: 3-22-2017
Time: 9:00

Initials: <u>C</u>A



Sump Pits	Clean	Oil Sheen 8	k Color	Comments
70k Room	<b> </b>	00000000000000000000000000000000000000		
6 Turbo Blower		Sump Water Diverted to Ash Pit		
7 Generator	-==	Sump Water Diverted to Ash Pit		
5 Turbo Blower	//	Sump Water Diverted to Ash Pit		
7 Turbo Blower				
2300VAC Room	<b>V</b>	**************************************		
8 Generator		Sump Water Diverted to Ash Pit		


If oil is found in sump pit contact KM to have the pit cleaned out.

Pit covers must remain on at all times

Date: 3/2/17

Time: 1800

Initials: R



Sump Pits	Clean	Oil Sheen & Color	Comments
70k Room	~		
5 Turbo Blower		Sump Wate	r Diverted to Ash Pit
7 Generator		Sump Water Diverted to Ash Pit	
5 Turbo Blower		Sump Water Diverted to Ash Pit	
7 Turbo Blower	A		
2300VAC Room	\$000mmmoronoom		
8 Generator	300000000000000000000000000000000000000	Sump Water Diverted to Ash Pit	

If oil is found in sump pit contact KM to have the pit cleaned out.